April 4, 2003

TO:	Internal File									
THRU:	Daron R. Haddock, Permit Supervisor									
FROM:	David Darby, Senior Reclamation Specialist									
RE:	2001, 2nd, Quarter Water Monitoring, Canyon Fuel Co., Gordon Creek 2,7, & 8, C/007/016-WQ01-2									
	submitted for all of the MRP required sites? y sites not monitored and reason why, if known:	YES[]	NO [X]							
The opminesite.	perator did not report flow for site 2-11-W, the Left l	Fork of Bryner	Cyn. Above the							
See Technical	tate does the MRP require a five-year resampling Directive 004 for baseline resampling requirements omittal when responding to question one above. Indement.	s. Consider the	five-year							
Resan	apling due: Permit expires 08/28/2004									
	equired parameters reported for each site? ents, including identity of monitoring site:	YES[]	NO [X]							
See #1 ab	ove. All other parameters were reported.									
	gularities found in the data? ents, including identity of monitoring site:	YES[]	NO [X]							

5.	Were	DMR	forms	submitted	for a	all	required	sites?	•
----	------	------------	-------	-----------	-------	-----	----------	--------	---

Identify sites and months not monitored:

1st month, YES [X] NO []
2nd month, YES [X] NO []
3rd month, YES [X] NO []

6. Were all required DMR parameters reported?

YES [X] NO []

Comments, including identity of monitoring site: There were no discharges during the quarter.

7. Were irregularities found in the DMR data?

YES [] NO [X]

Comments, including identity of monitoring site:

8. Based on your review, what further actions, if any, do you recommend?

Contact the Chris Hansen to see if they have data for the 2nd Quarter for 2-11-W.

O:\007016.GC2\WATER QUALITY\WQ_01-2.DOC